



JBL PROFESSIONAL PRODUCTS

REPAIR KIT "GOES INTO" LISTING

Revision AR -- June 14, 2004

Replaces Rev. AQ - March 23, 2004

*See page 22 for explanation of notes

NOTES	REPAIR KIT	SUGGESTED RETAIL	KIT GOES INTO
	Obsolete C16R2115	-	LE8TX, 2115, 2115B, 2115J
	C16R2118	\$82.00	2118J, 2118J-1
	C16R2123J	\$192.00	2123J
	C16R2168J	\$110.00	2168J
	C16R2202	\$162.00	2202B, 2202J
	Obsolete C16R2204	-	2204J
	C16R2206	\$118.00	2206J
	C16R2215	\$174.00	150-H (very old), 2215, 2215B
x	C16R2220	\$176.00	130BP, 2220B, 2220C, 2220J
x	C16R2225	\$138.00	2205B, 2205C, 2205J, 2225J
	C16R2226	\$128.00	2226J
	C16R2250	\$158.00	2250JPL (124-31005-00X)
	C16R2251	\$180.00	2251J (124-31002-01)
	C16R2254	\$204.00	2254J (124-37005-01)
	C16RE120	\$150.00	M21-16, M22-16, D120F-6, K120-16, E120-16 023125A, 023125J
x	C16RE130	\$164.00	D15S, M31-16, M32-16, D130F-6, E130-16, E140-16 K130-16, 970302-A
x	C16RE140	\$154.00	M41-16, M42-16, D140F-6, E130-16, E140-16, K140-16, 970402, 970402A
	C16RE145	\$172.00	M46-16, E145-16, M45-6
	C16RK110	\$144.00	M11-16, M12-16, D110F-6, E110-16, K110-16
	C16RK145	\$240.00	M45-6, K145-16
	C4R2226	\$128.00	2226G
	C4R2240	\$216.00	2240G
	C4R2241	\$140.00	2241G, 2241GPL (71126-03X)
	C4R2256	\$200.00	2256G (339548-001X)
	C4R252	\$162.00	252G (124-22001-01X)
	C4RCENT500	\$112.00	C500G (331366-001X), LSR32 LF
	Obsolete C4RE130	-	M31-4, M32-4, M35-4, D130F-2, E130-4, K130-4, 70777022
	C4RE155	\$190.00	E155-4
	C4REON10P	\$110.00	EON POWER 10
	C4RK110	\$144.00	M11-4, K110-4
	C4RK120	-	M21-4, D120F-2, K120-4
	Obsolete C4RK140	-	M41-4, D140F-2, K140-4, 970401-A
	C4RK145	-	M45-4, K145-4
	C4RK151	\$228.00	M51-4, K151-4
D	C4M35	-	M35-4, 70777022, REPLACED BY C8RE130
	C2R218	\$110.00	218F (124-58002-01)
	C2R252	\$162.00	252F (124-22001-01X)
	C2REONSUB	\$106.00	EON POWER SUB
	C2REON15P	\$112.00	EON POWER15
	C2REON15P-2	\$126.00	EON15-G2 LF
	C8R104-2	\$48.00	104H-2, 104H-3



JBL PROFESSIONAL PRODUCTS

REPAIR KIT "GOES INTO" LISTING

Revision AR -- June 14, 2004

Replaces Rev. AQ - March 23, 2004

*See page 22 for explanation of notes

NOTES REPAIR KIT	SUGGESTED	
	RETAIL	KIT GOES INTO
C8R115	\$76.00	115H
Obsolete C8R115H-1	-	115H-1
C8R116A	\$146.00	116A, 116H
C8R116H-2	\$94.00	116H-2
C8R116H-3	\$76.00	116H-3 (67071-01X)
Obsolete C8R119HS	-	119HS (Obsolete - Use C8R119HS-1)
C8R119HS-1	\$118.00	119HS, 119HS-1
C8R127A	\$118.00	127A
C8R127H-1	\$84.00	127H-1 (66265X)
C8R128H	\$176.00	128H
C8R128H-1	\$164.00	128H-1
C8R129H	\$154.00	129H
C8R1400ND	\$156.00	1400ND
C8R1400PRO	\$134.00	1400PRO
C8R2012	\$114.00	2012H, 2012HPL (124-56000-00)
C8R2020	\$116.00	2020H, 2020HPL
C8R2022	\$118.00	2022H (72778-01X)
C8R2023	\$90.00	2023H (337215-001X)
Obsolete C8R2025	-	2025HPL
C8R2032	\$138.00	2032H (318219-001X)
C8R2033	\$124.00	2033H (124-37007-00X)
C8R2035	\$138.00	2035HPL (73890X)
C8R2035-1	\$144.00	2035HPL-1
C8R2042	\$190.00	2042H (311693-001X)
Obsolete C8R2108	-	2108, 2108H
Obsolete C8R2110	-	2110, 2110H
C8R2115	\$168.00	2115A, 2115H
C8R2118	\$82.00	2118H (62526-02)
C8R2119	\$70.00	2119H (124-28000-00X)
C8R2121	\$194.00	2121, 2121H
C8R2122H	\$192.00	2122H
C8R2123H	\$192.00	2123H (59618-03)
C8R2125	\$238.00	2125
C8R2142	\$86.00	2142H
Obsolete C8R2145ALF	-	2145ALF
Obsolete C8R2145LF	-	2145LF
N/A C8R2150HF	-	*FSO*, 2150, 5A415
Obsolete C8R2150LF	-	2150, 5A415
C8R2152	\$160.00	2152H
C8R2155	\$272.00	2155H
C8R2169	\$102.00	2169H (339111-001X)
C8R2202	\$162.00	2202A, 2202H
Obsolete C8R2203	-	2203A, 2203H
C8R2204	\$160.00	2204H
C8R2206	\$118.00	2206H, 2206HPL



JBL PROFESSIONAL PRODUCTS

REPAIR KIT "GOES INTO" LISTING

Revision AR -- June 14, 2004

Replaces Rev. AQ - March 23, 2004

*See page 22 for explanation of notes

NOTES	REPAIR KIT	SUGGESTED RETAIL	KIT GOES INTO
x	C8R2212	\$272.00	123A-1, 2212, 401-133
	C8R2213	\$186.00	2213, 2213H (58963-03X)
	C8R2214	\$128.00	2214H (65975-01)
	C8R2215H	\$198.00	2215A, 2215H
	C8R2217	\$126.00	2217H, 2217HPL (74704)
x	C8R2220	\$176.00	130AS, 2220A, 2220H
x	C8R2225	\$138.00	2205A, 2205H, 2225H
	C8R2226	\$128.00	2226H, 2226HPL
	C8R2227	\$154.00	2227H, 2227HPL
x	C8R2235	\$130.00	2230A, 2231A, 2231H, 2234H, 2235H
	C8R2240H	\$204.00	2240H, 2245H, E155-8,
	C8R2241	\$140.00	2241H
	C8R2242	\$148.00	2242H, 2242HPL
	C8R2245H	\$216.00	2245H (60513X), 2240H, E155-8
	C8R2250	\$164.00	2250HPL
	C8R2255	\$170.00	2255HPL
	C8R2258	\$198.00	2258HPL
	C8R2262	\$130.00	2262H (338312-001X)
x	C8RE120	\$150.00	M20, M21, M22-8, D120, D120F, E120-8, K120 D131, D131F, 2130, 092577, 092577-A, 092577H
	C8RE130	\$164.00	M30, M31, M32-8, D130, D130F, D130H, E130-8 E140-8, K130, 2135, 023101, 023101A, 023101H
x	C8RE140	\$154.00	M40, M41, M42-8, D140F, E130-8, E140-8, K140, 043091, 043091-A, 043091H, 970401, D140R
	C8RE145	\$172.00	M46-8, E145-8
	C8RE155	\$190.00	M55-8, E151-8, E155-8, 2240H, 2245H
	C8REON15	\$116.00	EON15 PASSIVE
	C8REON10-G2	\$92.00	EON10-G2 LF, EON10 PASSIVE LF
	C8REVO	\$138.00	EVOi324 LF
	C8RG125	\$154.00	G125-8, G125A-8
	C8RG125B-8	\$156.00	G125B-8
	C8RG135	\$300.00	G135-8
	C8RG135A	\$200.00	G135A-8
	C8RK110	\$144.00	M10, M11, M12-8, D110F, E110-8, K110, 2120 043109, 043109-A, 043109H
	C8RK145	\$240.00	M45, K145
x	C8RK151	\$228.00	K151, K151-16
	C8RLE10H-1	\$202.00	LE10H-1, LE111A, LE111H
	C8RLE111A	\$196.00	LE111A, LE10H-1, LE111H
	C8RLE111H	\$170.00	LE111H, LE111A, LE10H-1
Obsolete	C8RLE15B	-	2216
	C8RLE510	\$86.00	LE5-10, LE5-12
	C8RLE52	\$76.00	LE5-2
Obsolete	C8RLE59	-	LE5-9, 2105, 2105H, 2150 HF



JBL PROFESSIONAL PRODUCTS

REPAIR KIT "GOES INTO" LISTING

Revision AR -- June 14, 2004

Replaces Rev. AQ - March 23, 2004

*See page 22 for explanation of notes

NOTES	REPAIR KIT	SUGGESTED RETAIL	KIT GOES INTO
	C8RLE8T	\$162.00	LE8, LE8-1, LE8T, LE8T-H, LE8-101
Obsolete	C8RLT-1	-	SLT-1
	C8RM121	\$134.00	M121-8, M121-8PL
	C8RM151	\$166.00	M151-8, M151-8
	C8RM209-8A	\$64.00	M209-8A (124-28000-02X)
	C8RM222	\$112.00	M222-8
	C8RMI10	\$140.00	MI-10, MI10-1
Obsolete	C8RMI12	-	MI-12
Obsolete	C8RMI12-1	-	MI-12-1
	C8RMI15A	\$200.00	MI-15A, MI-15
	C8RU801C	\$208.00	801C
Obsolete	C8RU801RCA	-	801A, 801AA
Obsolete	C8RU801RCB	-	801B
	C8RU803	\$158.00	803
D	CR2290	-	PR15F, PR15R, 2290
Obsolete	CSB1003	-	Control™ SB-1 use C1003
Obsolete	CSB5003	-	Control™ SB-5 use C5003
	D16R2405	\$100.00	2405, 2405H, 2404H, 2404H-1 (62504-02X)
	D16R2410	\$234.00	LE175-200, LE175DLH, 2410, 5A350, MI11419
D	D16R2420	-	REPLACED BY D16R2421
x	D16R2421	\$244.00	2420, 5A355, 2421B
x	D16R2425	\$136.00	2421, 2425J, 2426J, 2427J
	D16R2440	\$204.00	375H, 2440, 5A360, MI11427
	D16R2441	\$224.00	2441
	D16R2445	\$162.00	2445J
	D16R2450	\$174.00	2450J, 2446J, 2447J, 2451J
	D16R2451SL	\$194.00	2451SLJ
Obsolete	D16R2460	-	LE100S, LE175HP, 2460, 5P350
	D16R2470	\$242.00	2461, 5P355, 2470, 2475J
	D16R2482	\$208.00	2480, 2482, 2485J
Obsolete	D16R375AB	-	375AB, 375EX, 375FH, 375HP, 5P360, MI11426, MI11426A
	D4R0175TI	-	0175TI, 2142H HF
Obsolete	D4R024	-	O24, SLT-1 HF
Obsolete	D8R034	\$110.00	O34
	D8R035TI	\$126.00	O35TI
	D8R035TIA	\$92.00	O35TIA, O37TI (69495X)
Obsolete	D8R044	-	O44
	D8R052TI	\$36.00	O52TI (74856X)
Obsolete	D8R066	-	O66
x	D8R075	\$110.00	075R, 2402, 2402H, 075-022, 075-105, 075-105B, 075-105C, 075-105CH, 075-105D,
	D8R076	\$144.00	2403, 2403H
Obsolete	D8R2145HF	-	2145, 2145A, 5A395
	D8R2406	\$110.00	2406H (337213-001X)



JBL PROFESSIONAL PRODUCTS

REPAIR KIT "GOES INTO" LISTING

Revision AR -- June 14, 2004

Replaces Rev. AQ - March 23, 2004

*See page 22 for explanation of notes

NOTES	REPAIR KIT	SUGGESTED RETAIL	KIT GOES INTO
	D8R2406-1	\$104.00	2406H-1 (337213-003X)
	D8R2407	\$120.00	2407H (339150-001)
	D8R2415	\$172.00	2415H
D	D8R2416	-	2416H (Use D8R2416-1)
	D8R2416-1	\$148.00	2416H-1, 2416H, 2155H HF, 2152H HF
	D8R2417	\$112.00	2417H (75716X)
	D8R2418	\$76.00	2418H (315436-001X), EON POWER15, EON 15
	D8R2418-1	\$74.00	2418H-1, EON15-G2 HF
	D8R2421	\$244.00	2421A
x	D8R2425	\$136.00	2425H, 2426H, 2427H
	D8R2430	\$128.00	2430HPL (125-30000-00X)
	D8R2431	\$130.00	2431H (339894-002X)
	D8R2435	\$756.00	2435HPL
	D8R2445	\$162.00	2445H
	D8R2450	\$174.00	2446H, 2447H, 2450H, 2451H, 2451H-1
	D8R2450SL	\$194.00	2450SL (74114X)
	D8R2490	\$214.00	2490H
Obsolete	D8R475ND	-	475ND
Obsolete	D8RLE20	-	LE20-1, 401-132
	D8RLE25	\$66.00	LE25, LE25-1
	D8RLE252	\$64.00	LE25-2
	D8RLE254	\$68.00	LE25-4
	D8RLE26	\$64.00	LE26
Obsolete	D8RU801DA	-	801A, 801AA

NOTES: D - Discontinued, use indicated replacement.

x - Closest substitute available

N/A - *FSO*, Factory Service Only, return to JBL Professional